



December 30, 2020

EOS: Master 1200 End of Service Notice

This is to inform you that effective immediately LMI will no longer be able to service the Master 1200. This End of Service (EOS) is driven by part obsolescence beyond LMI's control.

Service requests for the Master 1200 will be fulfilled with the Master 2400. The Master 2400 supports up to 24 sensors and has identical form factor, electrical connections, and functionality as the Master 1200.

In October of 2016, we announced the replacement of the Master 400, 1200, and 2400 products with the Master 810 for systems with up to 8 sensors, and the Master 2410 for systems with up to 24 sensors. All new systems should be designed using these latest generation products.

Part Description	Part Number	LTB Date	Estimated End of Service	Replacement Product
Master 1200	30649	none	January 31, 2020	Master 2400 (service requests) Master 810 or Master 2410

Note: The service period of repaired devices ends on the End of Service date indicated above.

The above information is effective immediately. If you have any questions, please contact contact@lmi3d.com or your LMI account manager.