



Revision: A

## chroma+scan 21x5 Release Notes

Version: 4.11.6.2 (previous version: 4.11.5.4)

### New Features:

---

#### *Support for B series sensors*

This release supports the 2125B sensor. Stations running older software are not compatible with the B sensors and will configure the sensor timing incorrectly. As such, all systems with B sensors must be upgraded to 4.11.6.2. The B sensors can be run in a system with older sensors (e.g. 2125 and 2125B in one system). Additionally, sensors running the previous release (4.11.5.4) are compatible with this station software (e.g., spare sensors running older firmware can be swapped into a system running 4.11.6.2 without having to run another upgrade).

---





Revision: A

## Fixes:

### *Detection mode failure*

Previously, Detection mode was not working when the settings field '*IoStateOutputEnable*' was set to 1 (enabled). This has been fixed.

### *IoStateOutputEnable setting behavior*

Previously, the field '*IoStateOutputEnable*' was always enabled regardless of the server settings file. This has been changed. If the server settings file does not contain the field, it will be enabled by default.

