

February 23, 2021

Firmware Update Notice: FocalSpec LCI1220 and LCI1620

This is an important notice that **future LCI1220 and LCI1620 sensors will require updated FocalSpec Firmware Release 1.4.1** due to the obsolescence of an internal component.

This new firmware is backwards compatible and can be used with all LCI1220 and LCI1620 sensors. Firmware version 1.4.1 is compatible with FocalSpec SDK Releases 2.0.0 and above.

LMI will begin delivering LCI1220 and LCI1620 sensors with Firmware Release 1.4.1 in April 2021.

Sensors which require the updated firmware will be identified by a serial number change.

- LCI1220 Serial numbers containing 'K' (xxxxxKxxxx)
- LCI1620 Serial numbers containing 'G' (xxxxxMxxxx)

The firmware updating tool, FocalSpec Sensor Maintenance Tool, has been updated to version 1.2.0, and will automatically prevent installing incompatible firmware.

FocalSpec Firmware Release 1.4.1 and Sensor Maintenance Tool 1.2.0 are available from [the Product Downloads page](#)

If you have any questions regarding this latest release, please email us at support@lmi3d.com.